PRINCIPAL	MR. DR. JOSEPH
ENROLLMENT	353 STUDENTS
SCHOOL OPENED	
SITE VISIT DATE	FEB., 2015

NOTE:

- DRAINAGE CHANNELS OVERFLOW INTO CLASSROOMS, RUNOFF SITS AND STAGNANTS
- SEWER CONNECTS TO GOV. SYSTEM, GREASE TRAP OKAY, NO ISSUES
- WATER CONNECTED TO GOV. SYSTEM, NO ISSUES W/ PRESSURE
- NO FIRE HYDRANTS ON CAMPUS
- ADEQUATE PARKING, AC. PAVEMENT IS IN BAD CONDITION.
- MOST KIDS BUSED, CONGESTED
- FENCE IN GOOD CONDITION
- SIDEWALKS GOOD, RAMP SLIPPERY
- PLAYGROUND OKAY,. GOOD CONDITION



OIA – ASSESSMENT OF BUILDINGS AND CLASSROOMS
US VIRGIN ISLANDS – ST. CROIX

HHF PLANNERS places for people

Austin Tsutsumi & Associates, Inc. Engineers & Surveyors

FIGURE 26

JUANITA GARDINE ELEMENTARY SCHOOL

DISCLAIMER: SITE PLAN FEATURES ARE CONCEPTUAL AND NOT INTENDED FOR DESIGN PURPOSES